



CASE STUDY: BG DYNAMIC ENGINE RESTORATION SERVICE

SERVICE BG Dynamic Engine Restoration Service

PRODUCTS BG Dynamic Engine Cleaner, PN 103192
BG Dynamic Engine Cleaner Rinse Oil, PN PE04-N1GA
BG Platinum® 44K®, PN 208
BG Advanced Formula MOA®, PN 115



VEHICLE:
2014 Nissan Altima
75,150 miles (120,942 km)

PROBLEM

Sludge buildup throughout the engine.

SOLUTION

The BG Dynamic Engine Restoration Service: a powerful, safe engine and fuel system cleaning service.

Features

- Removes oil sludge and varnish
- Restores compression
- Harmless to oil pumps, seals, and gaskets

Benefits:

- Lowers tailpipe emissions
- Reduces oil consumption
- Improves overall power and engine efficiency






SERVICE RESULTS

OIL FILL PORT



OIL SUMP



SUMMARY

BG Dynamic Engine Restoration cleaned the engine and removed oil sludge and varnish. The problems have resolved, and as a result, this vehicle will last longer and perform better.

Field Case Study submitted by: Team BG Associates, Inc.